ALDERSON ELECTRIC SANDERS

INFORMATION/DATA SHEET

- 1 48 VDC, 1,000-watt electric motor
- 2 240 VAC /48 VDC converter
- 3 CE Rohs certification
- 4 Minimum IP 65, modules are double insulated and circuit breaker protected
- 5 Machines use water with the range of abrasive discs
 - No dust
 - No overspray with new spray guard
 - Longer disc life
 - At least 8 times faster than anything else
 - No toxic stripper required
 - Removes <u>all</u> lead from the timber including lead that has been absorbed into the original bare timber
 - Meets preferred option for the AS/NZS 4361.2:2017 (3.5.4 (a))
- Waste is collected in an "Enviromat". This is a synthetic mat that lets water through while trapping all the lead paint waste particles. Test results show that 99.8% of the lead is collected by this mat with 0.02% leaching through the mat. This particular test recorded 2500 parts per million collected by the mat and only 20 parts per million leaching through. Putting this in perspective, the typical acceptable ground contamination around a kindergarten is 200 parts per million and in commercial areas it is 500 parts per million. See attached lab test results.



Laboratory Services

Auckland 52 Aintree Ave. PO Box 107028, Auckland Airport,

Tel: (09) 539 7614

Invercargill

(03) 214 4040

(03) 214 4041

142 Esk Street, PO Box 747, Invercargill, 9840

(03) 409 0559

74 Glenda Drive, PO Box 2614, Wakatipu,

Queenstown

clientsupport@water.co.nz

Certificate of Analysis Laboratory Reference:171212-112

Attention.

Richard Ord

Not Available

ALDERSON (NZ) LIMITED Client: 3 Unit 4, Loft Place, Kumeu, 0810 Address:

Total Metals by ICP-MS-Trace (Default Digest)

Client Reference: Purchase Order:

Lead (Total)

www.watercarelabs.co.nz

Paint Leachate

Report Issue Date Received Date:

252364-0 18-Dec-2017 12-Dec-2017

Sampled By: Quote Reference

13

Customer 4794

Sample Details	WATERS	WATERS	
Lab Sample ID:	171212-112-1	171212-112-2	
Client Sample ID:			
Sample Date/Time:	12/12/2017	12/12/2017	
Description:	Marmite Jar	Gutter Bolt Jar	
Metals			

Results marked with * are not accredited to International Accreditation New Zealand

20

Where samples have been supplied by the client they are tested as received. A dash indicates no test performed

Analyte	Method Reference	MDL	Samples	Location
Metals				
Total Metals by ICP-MS-Trace (Default D	Digest)			
Lead (Total)	In House based on EPA 200.8 by ICPMS	0.00010 mg/L	All	Auckland
Preparations		Version and the	Kennada III	ALL VE
Digest for Total Metals in Liquids	APHA (online edition) 3030 E (modified, 4:1 Nitric Hydrochloric Acid)		All	Auckland

Watercare Laboratory Services Auckland 52 Aintree Ave.

PO Box 107028. Auckland Airport.

Tel: (09) 539 7614 Fax: (09) 539 7801 Invercargill

142 Esk Street, PO Box 747. Invercargill, 9840

(03) 214 4041

74 Glenda Drive, PO Box 2614. Wakatipu. (03) 409 0559

clientsupport@water.co.nz

Certificate of Analysis Laboratory Reference: 180116-111

Attention:

Richard Ord

ALDERSON (NZ) LIMITED

3 Unit 4, Loft Place, Kumeu, 0810 Client Reference Paint Leachate

Purchase Order: Not Available

www.watercarelabs.co.nz

Final Report Report Issue Date

256510-0 24-Jan-2018 16-Jan-2018

Received Date: Sampled By: Customer Quote Reference 4794

Sample Details	WATERS	
Lab Sample ID: Client Sample ID:	180116-111-1	
Sample Date/Time:	09/12/2017	
Description:	Marmite Jar	
Metals		
Total Metals by ICP-MS-Trace (Default	Digest)	
Lead (Total)	mg/L 2500	

Results marked with * are not accredited to International Accreditation New Zealand

Where samples have been supplied by the client they are tested as received. A dash indicates no test performed.

Analyte	Method Reference	MDL	Samples	Location
Metals				
Total Metals by ICP-MS-Trace (Default Digest)				
Lead (Total)	In House based on EPA 200.8 by ICPMS	0.00010 mg/L	All	Auckland
Preparations				
Digest for Total Metals in Liquids	APHA (online edition) 3030 E (modified, 4:1 Nitric:Hydrochloric Acid)		All	Auckland

The method detection limit (MDL) listed is the limit attainable in a relatively clean metrix. If dilutions are required for analysis the detection limit may be higher For more information please contact the Operations Manag